

~~TOP SECRET~~

25X1A

DISPATCH NO. [REDACTED]-0076

Copy No. 1 of 2

21 July 1956

25X1A

TO : [REDACTED]  
FROM : [REDACTED]  
SUBJECT: GENERAL - OPERATIONAL

25X1A

Specific - [REDACTED]

25X1A

1. This is Commander's Report on Mission No. 1027 flown by [REDACTED]

25X1A

2. Mission Planning: Superior.

3. Pilot Performance: Results obtained by [REDACTED] were satisfactory but certainly not up to standards previously demonstrated. I am completely satisfied that he is entirely reliable for the mission.

4. Weather: As briefed except from Spokane area to Pocatello which varied from broken to overcast as compared to briefed clear.

25X1A

5. [REDACTED] used entire load but shutter malfunctioned early in flight. Quality of good product was excellent.

6. Electronics: 100% operational for the mission.

7. Aircraft and Equipment Trouble: Sextant out of adjustment.

8. Personal Equipment: Radio and Faceplate heat malfunctioned in seatpack and had to use emergency connections. Operation O.K. Found broken wire in seatpack.

25X1A

Enclosure:  
Annex 1 - Weather

155783  
ENCLOSURE NO. 155783  
CLASS. ☐  
EXEMPTED FROM AUTOMATIC  
DECLASSIFICATION  
DATE 7-31-86 BY 1100368  
7-31-86 REVIEWER

TS # 155783  
Copy 1 of 1 copies

~~TOP SECRET~~

T/S	#	DET-016
Page	1	of 1